


Insert POSITIVE TYPE / DOUBLE SIDE

- : Continuous cutting
- ◐ : Light interrupted cutting
- ⊗ : Heavy interrupted cutting

DX



**Rhombic, 55°
with hole**

[illegible][illegible]

*Corner radius (RE) with a sign of inequality (<) means minus tolerance.

● : Line up

Reference pages: External toolholder → **C039** - Internal toolholder → **D035** -